

Web Zone prerequisites

Introduction

zebrix allows you to integrate an existing website into your pages. However, the functionality of this feature is dependant on a variety of factors outside Zebrix, over which has no control. Zebrix just displays the content or not, depending on the parameters of the Web site.



We can not guarantee the proper display of external web content on your screens, just as we can not guarantee the proper operation of your zebrix screen when these third-party content is displayed.

This guide lists a bunch of the most common problems our users have and possible solutions to these problems.

- The site I'm trying to view does not appear in the Page Editor or in the Page Preview, but works on the screen

The zebrix CMS is secured by the HTTPS protocol, it limits the possibilities that your password or other private information can be intercepted by a malicious person.

When you try to display a non-secure website (whose address starts with `http:` and not `https:`), your internet browser forbids this “non-secure” site displays in the secure page editor because of its security policy. (All internet browsers work this way).

You can therefore preview in the page editor your sites only if they are in `https`. However, this should not be a problem on your screens, which are connected to `http` (the default).



It is possible to access to Zebrix in `http` (non-secure), you can then preview your non-secure site in the page editor, but we strongly advise against accessing Zebrix in an unsecured way.

- The site i integrated in a page is not displayed, neither in the zebrix interface nor on the screens

Some sites forbid to be integrated into another site. This option is usually set by the developer or administrator of the website you are trying to integrate. It is actually a common recommended setting for security reason.

This prohibition is defined by an `http` header set by the web server and taken into account by your web browser (and the integrated one into the display). One of these two following headers (or both) could prevent the web content to be displayed in the page editor or on the screen:

- “X-Frame-Options” (considered as deprecated my most recent web browsers)
- “Content-Security-Policy”

```
▼ Response Headers view source
Access-Control-Allow-Origin: https://cdn.praxis.nl
Cache-Control: max-age=900
Connection: keep-alive
Content-Encoding: gzip
Content-Language: fr
Content-Length: 21784
Content-Type: text/html;charset=UTF-8
Date: Tue, 13 Oct 2015 20:04:13 GMT
ETag: "086eab9d54dc47cc868298f4ee6a8fbad"
Expires: Thu, 01 Jan 1970 00:00:00 GMT
Pragma: no-cache
Server: Unknown-WS/prd0.01
Set-Cookie: LANGUAGE=fr; Path=/; Secure; HttpOnly
Set-Cookie: maxedaRememberMe=""; Expires=Thu, 01-Jan-1970 00:00:10 GMT;
Strict-Transport-Security: max-age=31536000; includeSubDomains
Vary: Accept-Encoding,User-Agent
X-Content-Type-Options: nosniff
X-Frame-Options: SAMEORIGIN
X-XSS-Protection: 1; mode=block
```

In the example above, the X-Frame-Options only allow website having the same domain (same origin) to embed it. As zebrix is considered as a different website (other domain name), the zebrix domain name has to be added in a whitelist.

Here is how the **X-Frame-Options** header can be set :

```
X-Frame-Options: Allow-From *.zebrix.net;
```

Here is how the **Content-Security-Policy** header needs to be adjusted:

```
Content-Security-Policy: frame-ancestors 'self' *.zebrix.net;
```

- The site I want to embed in my page displays ads or messages in the foreground, how can we make them disappear ?

Unfortunately, when you integrate a website in a web area, you are dependent on the content imposed by this website.

- The SAMSUNG screen freezes on the page that integrates the website I chose to display or, worse yet, it crashes or restarts

Unfortunately, we can not guarantee the proper functioning of a screen on which you integrate third-party web content that uses HTML, CSS, Javascript, Flash or other code that is not supported by the screen

But for some cases, if you're using a NUC, the firmware version could be the cause, is so, please contact our support : support.ds@manganelli.com

From:

<https://documentation.zebrix.net/> - **zebrix signage documentation**

Permanent link:

<https://documentation.zebrix.net/doku.php?id=en:webzone&rev=1674223952>

Last update: **2023/01/20 15:12**

