## Mise en place d'un proxy sur un NUC

Prérequis :

- clavier
- Souris
- 1 Brancher le clavier et la souris au NUC
- 2 Cliquer sur "F1"

S zebrix box configuration - ×
ID: 1c697aa37b69 Version: 19.06-03
🕟 zebrix
Network Display & Audio Touch Web admin
Network Settings (F2)
Network Diagnostic (CTRL+D)
Zebrix Server: screen.zebrix.net
Protocol:   http  http
No proxy server
O Proxy Address: ?
Proxy bypass list:
Europe: support@zebrix.net   +33 3 20 41 59 69 America: support@zebrix.us   +1 917-789-1179

Une fenêtre va s'ouvrir

## 3 - Cliquer sur "F2"

Une fenêtre va s'ouvrir 4 - Aller dans "Wired connection 1"



Une fenêtre va s'ouvrir

- 5 Aller dans l'onglet "Proxy" 6 Passe la méthode en automatique 7 Rentrer le proxy dans PAC URL
- 8 Sauvegarder, quitter et reboot le boitier

