

Bug list for the new SSSP9 screens

QMB series Tizen 6.5

Firmware : S-PTMWWC-1020.8

CRITICAL

- In rare cases the video does not start and the screen remains black

MAJOR

- In some cases the video does not start at 0s

MINOR

- Orientation in automatic mode is not recognized
- SSSP9 not detected by Zebrix, screen displayed as SSSP7
- Small slowdown when switching from one video to another
- Black micro flash between image and video
- Blocking of the playlist with the PIP

OPERATIONAL

- Simultaneous playback of videos
- Play 2 videos simultaneously
- Play 3 videos simultaneously
- IFRAME
- Playlist of images / Pages
- DATE / TIME area
- Launching App AUTO : 150 reboot

From:

<https://documentation.zebrix.net/> - zebrix documentation

Permanent link:

https://documentation.zebrix.net/doku.php?id=en:sssp9_-_1020&rev=1651128963

Last update: **2022/04/28 08:56**

